






## Risk assessment for : Coulsdon Home Hardware Ltd
















<b>Risk assessment name</b>	Plastering and Rendering	<b>Assessment type</b>	 General
<b>Assessor name</b>	Simon Harris	<b>Affected site(s)</b>	Signature Homes Ltd (CR5 2RA)
<b>Assessment date</b>	19/02/2020	<b>Review period</b>	Annually
<b>Approved by</b>	Simon Harris	<b>Review date</b>	19/02/2021
<b>Approved date</b>	19/02/2020	<b>Reference</b>	PLASTERING - 001

## Description

This Risk Assessment is to assess the risks with plastering & rendering.

Hazard	Who could be harmed and how?	Existing controls	Risk rating (L x S)
 Electrical Faults Leading to fire or electric shock.	Operatives	 All employees check equipment before use  All site supplies will be 110v  Electrical supply isolated before commencing work	1 x 1  <b>1</b>  Low

## Risk assessment for : Coulsdon Home Hardware Ltd

Hazard	Who could be harmed and how?	Existing controls		Risk rating (L x S)
 <p>Manual handling Tall, awkward &amp; unwieldy loads that are difficult to lift, transport and handle.</p>	Operatives	 Individuals have received information, instruction and training in manual handling techniques   Mechanical aids used where possible	 <b>Manual handling training</b> All staff are trained in Manual Handling and instructed to comply with good manual handling techniques.	1 x 1 1 Low
 <p>Respiratory/eye Irritation</p>	Operatives	 Adequate washing facilities on site   Correct PPE provided to all employees   Eye wash available	 <b>Area well ventilated</b>   <b>Ensure correct welfare and hygiene facilities are in place to avoid dermatitis</b>	1 x 1 1 Low
 <p>Slips, Trips and Falls Can occur if there is poor housekeeping within the workplace, also areas that are inadequately lit.</p>	Operatives	 <b>Avoid trailing cables</b>   <b>Handrails provided on all working platforms</b>	 <b>Correct safety boots worn</b>   <b>Walkways kept free from trip hazards</b>	1 x 1 1 Low

## Risk assessment for : Coulsdon Home Hardware Ltd


Hazard	Who could be harmed and how?	Existing controls	Risk rating (L x S)
 <p>Trapping/Entanglement Inadequate guarding on machinery could lead to operative getting clothing caught in the machinery.</p>	Operatives	<p>  Ensure cement/plaster mixers are regularly tested and inspected         </p> <p>  Staff trained in safe working practices for using cement/plaster mixers         </p> <p>  Only trained operators are allowed to use the machines         </p>	<p>1 x 1</p> <p>1</p> <p>Low</p>

## Further control measures

None required

### Risk rating explanation

Risk ratings are calculated by considering the likelihood of an event occurring along with the severity of the potential consequence should an accident occur. After considering existing control measures, values are assigned to the likelihood and severity from the scales below and these figures multiplied to established the risk rating.



9	18	27	36	45	54	63	72	81
8	16	24	32	40	48	56	64	72
7	14	21	28	35	42	49	56	63
6	12	18	24	30	36	42	48	54
5	10	15	20	25	30	35	40	45
4	8	12	16	20	24	28	32	36
3	6	9	12	15	18	21	24	27
2	4	6	8	10	12	14	16	18
1	2	3	4	5	6	7	8	9

Probability

Severity

### What do your risk ratings mean?

- Risk is categorised as LOW: Look to reduce risk if practicable
- Risk has been categorised as MEDIUM: Begin to plan your action to reduce the risk immediately
- Risk has been categorised as HIGH: Immediate action required to reduce the risk

Assessor's signature: Simon Harris

Approved by signature: Simon Harris